## Life Fitness 9100 Series Heart Rate and Telemetry Equipped Treadmills TROUBLESHOOTING GUIDE

Symptom: "Slowdown". Striding Belt slips during footfall or display reads "Press Start to Resume", or "Note Max. Speed Is Reduced To".

Malfunction	Probable Cause	Corrective Action
Striding Belt slips during footfall	Striding belt slips on front roller during stall test.	☐ Check striding belt & re-tension as necessary.
	Insufficient power source.	□ Plug treadmill into a dedicated 120V, 20 amp circuit. (See Operation Manual)
		☐ Inspect striding belt and deck for excessive wear. Replace any defective part.
Maximum speed is reduced	User is pushing striding belt.	☐ Inspect striding belt and deck for excessive wear. Replace any defective part.
	Wax system malfunction.  is spray pattern between 8" (200mm) and 16" (400mm)?  is nozzle clean?  is hose kinked?  is wax bag empty?  Is there a wax leak?  is the wax contaminated?  is manual waxing used?  Striding belt/deck malfunction:  Deck laminate is worn through.  Underside of striding belt is glazed over (hard, glossy)  There is a large build-up of wax, excessive wax fills fingernails when scratching underside of belt.	Replace deck and belt (Use unused side of deck, if available).  For 9100 with Telemetry only, reset stats & turn wax delay ON.  For 9100HR, update service menu.
		Call Life Fitness Customer Support Services 847-451-0036 or 1-800-351-3737