

# DELIVERY AND INSTALLATION

\*\*\*INSTALLER ALERT\*\*\*

## PowerMill: Discover – RPM Limit Error

Rev. IA-022818b



Life Fitness has been made aware of an issue for the PowerMill with Discover consoles generating a “RPM Limit Error” at max level 25. The models impacted are **INPMSE, INPMHD, & INPMDST**. Installers are to update the consoles software at installation to version **v3.07.33** for **Discover**. After the software has been updated installers are directed to test the unit at all levels and speeds to ensure that the “RPM Limit Error” has been resolved.

**MANAGERS:** Please go to <https://lfconnect.com/web/softwareDownload.html> and download the latest software update **v3.07.33 for Discover** to update your installers USB sticks.