NGS Troubleshooting

Alternator Wiring Diagram for StairMaster 4000, 4400, 4600 (PT only) (Prestolite, Yellow label)