Service Bulletin

Using 260-0952 Alternator with Pre-2016 Stairmaster Units

Applies to: 4000-Steppers + SC916 + SC5+ FreeClimber (155015) 7000PT + SM916 + SM5+ Gauntlet (150015)

Latest Rev. Service Manual

In 2018, a new alternator was introduced (260-0952) to replace the original Stairmaster alternator (SM22900). While this alternator is backwards compatible to pre-2016 units, the wires connect to it slightly different. Please see below:



W3 Field to F
W4 Tach to P
W5 Positive to B+
W6 Ground to B-