


Service Bulletin

Cleat Pin Backing Out On Triple Link Pedals

Applies to: Schwinn Triple Link Pedals

 **Enhanced Images:** Pictures can be zoomed in to any level for detail. Use the standard zoom tools for your platform to zoom in.

Links




Latest Rev.



Service Manual

On some Schwinn Triple Link Pedals, an issue has been identified where the pin that holds the pedal cleat to the pedal body can back out, rendering the clip inoperable. Please see image below.



If this occurs, the pedal will need to be replaced:

740-8825: 9/16" Threaded Triple Link Pedal Set.

740-8689: Morse Taper Triple Link Pedal Set w/SPD + LOOK Delta clip.

718-5869: Morse Taper Triple Link Pedal Set w/SPD + LOOK KEO clip.

For additional informations on pedals, please see doc [637-4501](#).