


SMA07 (new) and SME01.2 (exchange) Alternator Wiring Diagram
for StairMaster StepMill/7000PT (Prestolite, White label)



SMA07 can be used on StepMill/7000PT
Note: may have problems with lighter users.
Recommend SMC1003 instead.