

Customer Services Bulletin

Poor Battery Life

SC₅

An investigation of abnormal battery drain reports has led to a change in the electrical system used on the SC5.

To maximize performance, the battery and Lower Control Board (LCB) have been enhanced.

Should you have a drained battery on an SC5 before serial number **155005DAY12340116**, you must replace the LCB and battery together.

Battery Components:

Old Battery (Fig.1) PN: 14123
New Battery (Fig.2) PN: 055-0209



Fig. 1



Fig. 2

STAIRMASTER 1 of 2 637-1554 Rev: A



Customer Services Bulletin

Lower Control Board

• Old LCB (Fig. 3) PN: 13092

• New LCB (Fig . 4) PN: 055-0210

NOTE: To determine the version of the LCB, locate the green sticker on the LCB (Fig. 5). The old version of the LCB is labeled "PCK1N". The new version of LCB is labeled "PCN1N".







Fig. 4



Fig. 5

STAIRMASTER 2 of 2 637-1554 Rev: A