




StepMill Alternator (Prestolite yellow label)
Wiring Schematic