

Power Requirements

StepMill & Stepper

This document is to specify the electrical requirements for StairMaster StepMills & Steppers.

ATTENTION:

Consult an assistance of the certified electrician before installing, modifying or servicing any part of the electrical service for your equipment.

Facility Power Requirements When preparing your facility for new StairMaster StepMills or Steppers, it is important to have the correct electrical provisions in order for the equipment to operate safely and properly.

Requirement for Standard StepMill or Stepper

- 100-240 VAC
- Maximum 100 VA
- One plug needed

Requirement for Attached TV

- 100-240VAC,
- 50/60Hz,
- Maximum 1.2 A each
- Two plugs needed (one for the unit and another for the TV)

Note: Do not exceed the maximum current rating on any circuit breakers in your facility. Doing so may induce unexpected shutdown of equipment and possible user injury.