## Life Fitness 9100 Series Heart Rate and Telemetry Equipped Treadmills TROUBLESHOOTING GUIDE

Symptom: No Power

Malfunction	Probable Cause		Corrective Action
No Power	On/Off switch.		Is unit turned on?
	Insufficient power source.		Plug treadmill into a dedicated 120V, 20 amp circuit. Using a meter, verify power at outlet.
	Damaged line cord.		Replace line cord.
	Line cord improperly seated in socket.		Inspect power connection at wall outlet and at machine for proper contact.
	Faulty display console.		See "Display Console" symptom.
	Power module.  Circuit breakers  On/Off switch	0	Check connector P4 at CPU board for 120VAC. Replace faulty parts
	Interrupted circuit.		Test circuit breaker on treadmill. Replace if necessary.
Insufficient power	Display reads "Power up reset"		Verify power is a dedicated outlet. To verify, turn breaker at panel to off. Using a voltmeter, take a voltage reading at electrical outlet. With breaker off, zero volts should be detected.
			If voltage is present at electrical outlet, line is not wired for dedicated service.
		Ca	II Life Fitness Customer Support Services