
Life Fitness Models 9100, 9500HR, 9700HR, and 9700HR w/Decline Treadmills DIAGNOSTICS: SYSTEM TEST – WAXER ERROR MODE



Upon entry into this test the letterw WE (waxer errors) will be in the profile window. This test allows you to see the current wax motor error conditions.

The following is a list of the current waxer motor error conditions. If an error has occurred, refer to your troubleshooting section for corrective action.

WAXER MOTOR ERROR CONDITIONS

WAXER UNPLUGGED WAXER NO AC POWER

Press the 'CLEAR' key to exit the Waxer Errors test and return to the Waxer Manual test.