## Life Fitness 9100 Series Heartrate and Telemetry Equipped Treadmills TROUBLESHOOTING GUIDE

## **Symptom: NO TELEMETRY READING**

Malfunction	Probable Cause	<b>Corrective Action</b>
No Chest Strap detected.	Chest strap sensors not making good contact with body of user.	☐ Adjust chest strap
		Moisten sensors to make better contact with skin
	Loose connection at receiver.	☐ Check connection on receiver (See "How To")
	User is out of monitoring range.	☐ Move within three feet (1 meter) of receiver
	Faulty receiver.	☐ Replace receiver
	Faulty chest strap.	□ Replace chest strap
Erratic Heart Rate readings (Cross Talk)	Treadmills are located less than 8" (203 mm) apart.	□ Position treadmills to recommended distances (See Operation Manual)
Display reads "Chest strap not Detected"	Telemetry turned "OFF"	□ Enter EA mode and turn telemetry to "ON"
	Receiver is turned slightly sideways	Position receiver so it is horizontal with the console. (See "How ToRemove and Replace the Telemetry / HR Unit")
	Bad connection at Telemetry cable and receiver	☐ Check cable jack and receiver connection.
	Bad connection at console	☐ Reseat telemetry cable at console PCB.
	Receiver is 180° out of position	☐ Turn receiver 180°
		Call Life Fitness Customer Support Services 1-847-451-0036 or 1-800-351-3737