## Life Fitness 9100 Series Heart Rate and Telemetry Equipped Treadmills TROUBLESHOOTING GUIDE

## Symptom: Striding Belt Not Centered On Deck

Malfunction	Probable Cause	Corrective Action
Striding belt mis-alignment	Improper walking/running.	
	Striding holt tongion needs to	See How To Adjust and Tangian the
Striding belt not centered	Striding belt tension needs to be adjusted.	See How To Adjust and Tension the Striding Belt
		Call Life Fitness Customer Support Services
		847-451-0036 or 1-800-351-3737

NOTE: Also refer to Symptom: "Belt Beyond Limits" or "Notify Maintenance-Belt Tracking Error"