



G3 8 Stack Multi Station			
Model #:	PMS80-G#		Year 2007
Drawing #:	MS80-A25A		
Material #:	MMS0105-00		
Rev.: 1.1	Date: 9/25/2007		

Reference Number	Part #	Description	Notes
AG1	025706-B	Painting;Grip Set;;MS21-G2;;;MS21;MS21-	
AG2	089904	Grip Set;High	
			Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	025711-B	Upper Connecting Ring, Polarized Titanium (MS50G2)	
G11	009371-E	Cap;Grip;GM03	
G12	000603-B	Foam Grip;31.8x5tx337.9L	
G13	000604-D	Foam Grip;Straight;25.4x5tx150L	
G15	1000097443	Connecting Plate;Lower	
G33	009372-E	Cap;Grip;GM02	
G34	009355-B	Stopper Mast;Foam;AL6061;GM02	
G34	009355-B	Stopper Mast;Foam;AL6061;GM02	
Not Shown	004519-AE	Screw;Round;Hex Socket;M10x1.5Px80L	Order 4 for connection ring
Not Shown	004555-AB	Screw;Hex Socket;Round;M10x1.5Px25L;Cr;A	Order 4 for connection ring
Not Shown	020465-AB	Washer;Flat;M10.2X25PX2.0T;Chromed	Order 8 for connection ring
Not Shown	004535-AC	Screw;Hex Socket;Round;M8x1.25Px30L	Order 24 for connection ring
Not Shown	005042-00	Washer;Flat;8.2X30.0X2.0T;Black Zinc	Order 24 for connection ring
Not Shown	004943-00	Nut;Nylon;M10x1.5P;Cr Plate;	Order 4 for connection ring
Q06	008456-A	Connecting Plate, FW62 Aluminum Cover Board Connecting Plate,	
Q07	015954-AA	MS50-Q07	
Z10	004943-00	Nut;Nylon;M10x1.5P;Cr Plate;	
Z11	004846-AE	Set Screw;M8X1.25PX10L	
Z12	005007-00	Washer;Spring;12.2x21.5x3.0t	
Z14	004519-AE	Screw;Round;Hex Socket;M10x1.5Px80L	
Z15	004780-AC	Screw;Umbrella Hex Scoket;M10x1.5Px25L	
Z16	004781-00	Screw;Hex Socket;BH;M8x1.25Px25L;Adhere;	

Z19	004560-AD	Screw;Hex Socket;Sink;M6x1.0Px20L;Adhere	
Z21	004855-AC	Set Screw;M6X1.0PX4L	
Z22	008523-B	Washer;Arc;M10x28x10.5T;SS41	
-	-		For Adj Pulley Left (MS24) - see individual list
-	-		For Adj Pulley Right (MS25) - see individual list
-	-		For Lat Pull (MS51) - see individual list
-	-		For Tricep Ext (MS52) - see individual list
-	-		For Low Row (MS530) - see individual list
Not Shown	090365	Hardware Pack	
			Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	1000106249	Painting;CON Tube Set;U;MS50-G2;;;;;MS50;	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	1000106249	Painting;CON Tube Set;U;MS50-G2;;;;;MS50;	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	1000106249	Painting;CON Tube Set;U;MS50-G2;;;;;MS50;	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4

AG4	025711-B	Upper Connecting Ring, Polarized Titanium (MS50G2)	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	025711-B	Upper Connecting Ring, Polarized Titanium (MS50G2)	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	1000106249	Painting;CON Tube Set;U;MS50-G2;;;MS50;	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	025711-B	Upper Connecting Ring, Polarized Titanium (MS50G2)	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	1000106249	Painting;CON Tube Set;U;MS50-G2;;;MS50;	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4

AG4	025711-B	Upper Connecting Ring, Polarized Titanium (MS50G2)	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	1000106249	Painting;CON Tube Set;U;MS50-G2;;;;;MS50;	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	025711-B	Upper Connecting Ring, Polarized Titanium (MS50G2)	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	025711-B	Upper Connecting Ring, Polarized Titanium (MS50G2)	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	1000106249	Painting;CON Tube Set;U;MS50-G2;;;;;MS50;	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4

AG4	1000106249	Painting;CON Tube Set;U;MS50-G2;;;MS50;	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	025711-B	Upper Connecting Ring, Polarized Titanium (MS50G2)	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	1000106249	Painting;CON Tube Set;U;MS50-G2;;;MS50;	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	1000106249	Painting;CON Tube Set;U;MS50-G2;;;MS50;	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	025711-B	Upper Connecting Ring, Polarized Titanium (MS50G2)	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4

AG4	025711-B	Upper Connecting Ring, Polarized Titanium (MS50G2)	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	025711-B	Upper Connecting Ring, Polarized Titanium (MS50G2)	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	1000106249	Painting;CON Tube Set;U;MS50-G2;;;;MS50;	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	1000106249	Painting;CON Tube Set;U;MS50-G2;;;;MS50;	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	025711-B	Upper Connecting Ring, Polarized Titanium (MS50G2)	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4

AG4	1000106249	Painting;CON Tube Set;U;MS50-G2;;;;;MS50;	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	1000106249	Painting;CON Tube Set;U;MS50-G2;;;;;MS50;	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	025711-B	Upper Connecting Ring, Polarized Titanium (MS50G2)	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	025711-B	Upper Connecting Ring, Polarized Titanium (MS50G2)	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	025711-B	Upper Connecting Ring, Polarized Titanium (MS50G2)	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4

AG4	1000106249	Painting;CON Tube Set;U;MS50-G2;;;;;MS50;	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	1000106249	Painting;CON Tube Set;U;MS50-G2;;;;;MS50;	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	025711-B	Upper Connecting Ring, Polarized Titanium (MS50G2)	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
AG4	025711-B	Upper Connecting Ring, Polarized Titanium (MS50G2)	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring: 1000106249 x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
Not Shown	1000106249	Painting;CON Tube Set;U;MS50-G2;;;;;MS50;	Discontinued - Materials needed for connection ring and necessary hardware:Connection ring: 1000106249 x 1Hardware needed:004519-AE x 4,004555-AB x 4,020465-AB x 8,004535-AC x 24,005042-00 x 24,004943-00 x 4
Z12	005018-00	Washer;Spring;SW12 12.2X21.5X3T;Chromed	Discontinued