



6-Pin Connector to isolation board.

5 Pin Jumper (P9) for Display Power

2 Pin Connector (P15). Power to Isolation Board

How to tell if your MCB is LST853E (GK58-00002-0118)